

SUBJECT: **Condensate Control**

EFFECTIVE DATE: October 25, 2010

INTERPRETATION NUMBER: ADM – 3.0310.2

SEE ALSO: 2006 UMC – Section 310.2

INTERPRETATION SUMMARY

As an approved alternate to providing secondary overflow condensate drainage, this Department will approve the use of floatation switches that will deactivate the unit if the primary drains become clogged.